UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,923,979 B2 DATED : August 2, 2005

INVENTOR(S) : Fotland et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10,

Line 6, "tribolelectrically" should be -- triboelectrically --.

Column 12,

Line 41, "dielectric: substrate" should be -- dielectric substrate --.

Signed and Sealed this

Thirteenth Day of June, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office